

July 28, 2009

**CITY OF WHITESVILLE**  
**KIA 2007 Project**  
**Sanitary Sewer System Rehabilitation Project**  
**Manholes, Sewer & Pump Stations Rehabilitation**  
**KIA No. SX21059018**  
**SAI KY200611161451**

**FINAL INSPECTION REPORT**

Attendees:

Rick Thompson	City of Whitesville
Dan Forton	A&W Maintenance
Lenny Thrasher	HRG, PLLC

1. A&W Maintenance touched up epoxy liner under concrete cap of Pump Station (P.S.) #3 (behind Dollar Store). Epoxy coating/lining was in excellent shape. All pump hardware was functioning properly.
2. Checked P.S. #2 (behind doctor's building). Epoxy coating/lining was in excellent shape. All pump hardware was functioning properly.
3. Checked P.S. #6 (near senior citizen building). (Wet well was not coated for this project.) All pump hardware was functioning properly.
4. Checked epoxy coated manholes in the Green Street area. All were well coated with epoxy and the epoxy was soundly adhered to the manhole walls.
5. Checked epoxy coated manholes in the Oak Street area. The manholes in this area were previously in the worst condition. All were well coated with epoxy and the epoxy was soundly adhered to the manhole walls.